## Savoy School, Washington DC

The gymnasium in this school had severe elevation problems in some areas and was not suitable for the wood flooring system they wished to install for their basketball court. We were able to fix these problems and deliver a level and smooth floor.

